



Recall Notice 03-25-02

We recently shipped to you an NCE Corp, Radio Base Unit, RUB-01. It is possible that the Base unit software may be an incorrect version, causing only the Radio Base Unit, not either of the cabs, to function improperly. There is a simple test you can perform to determine if you may have a defective Radio Base Unit:

- 1) You need two cabs of any style to perform the test. You can have two ProCabs, two intermediate cabs, or one of each.
- 2) For the test, the relative cab addresses must not be more than **4 digits** apart, ie., a ProCab at address #15 and an intermediate cab at # 19.
- 3) Operate each cab one at a time, by itself, in the radio mode to verify its functionality with other cab off.
- 4) Then operate the cab that has the higher cab address by itself and with that cab operating start to operate the other cab with the lower address and observe the radio indicator LED on lower numbered cab.
- 5) If the **upper** numbered cab's **LED goes out** or if the cab does not function normally, then your Radio Base Unit must be upgraded by returning to NCE Corp with a copy of this notice. (899 Ridge Rd., Webster, NY 14580)
- 6) If both cabs operate normally your Radio Base Unit has the proper software.